

I'm not robot



Peugeot 207 cc roof problems

Peugeot 207 cc issues. Peugeot 207 cc roof won't open. 207cc roof not working. Peugeot 207 roof problems. Peugeot 207 cc roof.

When Neil's Peugeot 207CC wouldn't shut its roof due to the "roof down" switch malfunctioning, he sought help before taking it to the dealer. Chris suggested that a manual reset might resolve the issue, but this method didn't work for Neil. Users shared their experiences with similar problems and offered potential solutions. Some mentioned that specialists may be able to fix the issue more efficiently than dealerships. One user, Eileen, had a similar problem where the roof wouldn't close properly, prompting another user, Karen, to ask if she could try a solution involving a pen stuck in a reset button. The conversation revealed varying degrees of success with different solutions and highlighted the importance of consulting specialized forums or Peugeot dedicated websites for more accurate information. Some users expressed frustration with the complexity and cost associated with car maintenance issues like this one. I believe the Bosch electrics fitted to French cars may be of lower quality compared to those installed in German cars. Hello, this is my second post today. Hopefully it's not spamming. Peugeot 207cc 2008. While installing an aftermarket head unit and reverse camera, I encountered issues with the roof. The camera was mounted flush with the driver's side rear number plate. Wires were run along the metal arm and then down the trim on the driver's side. Removing trim along the driver's side passenger window didn't cause any existing cables to be disturbed. However, I had trouble screwing in the inside door handle as I damaged the nylon captive nut casings. The roof's movement seems to be incomplete upon startup, with messages displaying "Roof movement not completed," "Automatic door locking activated," and "Economy mode" on the display. Additionally, the boot is sometimes locking itself without any input. After topping up hydraulic fluid with fork oil and ensuring the battery was fully charged, I could hear the microswitches clicking in the roof switch but couldn't get the car to open the roof. Any assistance would be greatly appreciated. Economy mode seems activated after engine shutdown to preserve body computer voltage, which is never off. The radio also doesn't function when this mode is active. However, it clears when starting the engine. I suspect that economy mode might be a red herring in my case and only displayed when turning the key a few clicks. The car runs fine otherwise, but the radio occasionally reverts to demo mode, likely due to incorrect wiring. The roof movement appears to be caused by something else. I've checked hydraulic fluid levels, which seem sufficient. You're back on track, and that's great. Have a double-check at the reverse camera mounting spot since you weren't sure about any obstructions behind the number plate. Also, verify there isn't any wiring damage from drilling into the boot lock/no.plate light area.